



Step 2. Loosen this fitting and move hose aside.

Step 3. Loosen fitting and slide suction hose into reservoir.

Step 5. Remove mounting bolt and remove reservoir. Reverse instructions to reassemble.

Step 4. Remove the indicated items.

Oil immersion heater replacement for Advance model 6150 only.
Once reservoir is free of the enclosure, spin out defective heater, clean the threads, wrap new heater threads with Teflon tape and tighten firmly.
Questions, call 800-843-3625

Step 1. Drain reservoir, drain plug located under enclosure.